

KING AIR



NATION

www.KingAirNation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-42 PCE-94707

| | |
|--------------|-------|
| TTSN | 6,134 |
| TCSN | 6,265 |
| TSO | 3,213 |
| CSO | 3,005 |
| TSHSI | 0 |

| PART # | SERIAL # | DESCRIPTION | CSN | CYC LIMIT | CYC REM |
|---------------|-----------------|-------------------------------|------------|------------------|----------------|
| 3041501 | 85A326 | Rotor Compressor | 6,265 | 30,000 | 23,735 |
| 3023112 | A001TWFF | Compressor Disc 2nd Stage | 3,005 | 20,000 | 16,995 |
| 3023113 | A001T5YN | Compressor Disc 3rd Stage | 3,005 | 20,000 | 16,995 |
| 3036793 | 9E906 | Impeller | 6,265 | 20,000 | 13,735 |
| 3041431 | 85A326 | Compressor Turbine Disc | 6,265 | 10,000 | 3,735 |
| 3029312 | 86A101 | 1 st Stage PT Disc | 6,265 | 30,000 | 13,735 |
| 3029313 | 86A114 | 2 nd Stage PT Disc | 6,265 | 30,000 | 13,735 |

ADDITIONAL INFO:

- REMOVED IN JUNE, 2020
- STANDARD AERO OVERHAUL IN 2006
- FRESH HSI FROM TIA

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. King Air Nation is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.