

KING AIR



N A T I O N

kingairnation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-135

PCE-92097

TTSN	5924.6
TCSN	6336
TSO	232.2
CSO	219
TSHSI	0

PART #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3013111	Hub Assembly	6117	19,000	12,883
3013712	Compressor Disc 2nd Stage	6117	28,000	21,883
3011713	Compressor Disc 3rd Stage	6117	25,000	18,883
3013176	Impeller	6117	19,000	12,883
3014211	Compressor Turbine Disc	6117	16,000	9883
3022312	1 st Stage PT Disc	6117	30,000	23,883

ADDITIONAL INFO:

- Overhauled by Turbines, Inc.
- Fresh HSI & Repair by Turbines Inc. 2025
- CT Blades New at OH (TSN: 232.2)

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. King Air Nation is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.