

Contact: Carl Davis 200 Jetport Rd. Brandon, MS 39047 Phone: 601-936-0777

PT6A-112 PCE-12594

TTSN	10,934.1		
TCSN	4522		
TSO	1934.1		
CSO	842		
TSHSI	due		

PART #	DESCRIPTION	CSN	CYC	CYC
			LIMIT	REM
3013111	Hub Assembly	842	19,000	18,158
3013712	Compressor Disc 2nd Stage	2431	24,000	21,569
3011713	Compressor Disc 3rd Stage	4522	25,000	20,478
3013176	Impeller	4522	19,000	14,478
3013411	Compressor Turbine Disc	4522	16,000	11,478
3031012	1 st Stage PT Disc	4522	20,000	15,478

ADDITIONAL INFO:

• Overhauled by SECA 9/2011